Red Bride

Weir spillway

Existing Creek restored

New Footpath crossing the creek

Stone paved open space

Existing Island restored

Gazebo

New Path

Historical Path restored

Accessble Path

New Secondary Path

Existing Steps refurbished

Weir spillway

Existing Path widened/refurbished

Bridge

Graveled open space

Bridge

Existing Stone Lantern

Overlook with bench

Wooden Bench

Bridge

Upper Gazebo (optional)

New Secondary Path

Existing Path

Stone bridge installed 2018

Bench

Garden Entrance with stone steps

Lily Pond Cascade 2018 construction

CRANBROOK RD.

0   10   30ft

Image Sketch 1

CRANBROOK JAPANESE GARDEN

Image sketch for the new bridge to the island view North

Image Sketch 2

CRANBROOK JAPANESE GARDEN
MASTER PLAN sheet 1 of 3 (in color)